Release date: October 11, 2001
Ref. No.:S56kV212

S5000/S6000 V2.12 Operating System Upgrade

This is to announce the release of V2.12 operating system for the S5000 and S6000 MIDI Stereo Digital Samplers. This is a maintenance release with the following corrections to V2.11a.

[Corrections]

1. When transferring sample files via USB with ak.Sys., the sample may have a click noise. However, this problem also is related to the configuration of the computer system. - fixed

2. In the SMF Player mode, when starting playback of a Song from any bar past bar 1 (e.g. bar 8), all notes from bar 1 to the bar specified in the "at bar" field will be transmitted at once from the MIDI OUT - fixed

It now only transmits MIDI Program Change, Control Change, etc. up to the bar where playback was started, before beginning playback of the Song.

[Note]

1. No operator's Manual or Addendum has been release for V2.12 since there are no operational changes implemented in the new software.

Akai Musical Instrument Corp., 4710 Mercantile Drive, Ft. Worth, Texas 76137
Phone:(817) 831-9203 - Fax:(817) 222-1490
website:http://www.akaipro.com
In Canada, contact Power Music Marketing, 6415 Northwest Drive, Mississuaga, Ont, Canada L4V 1X1
phone:(905)405-1229 - fax:(905)405-1885