

Setting Samples


Standard Crunch Sound




Hard Overdrive Sound




Mild Crunch Sound





Bright Clean Sound




Use the BRIGHT IN jack









Boss FBM 1 patches

