

WIRING DIAGRAM


M 88 N




M 88 N(T)



M 88 N(6)



M 88 N(C)



Positive pressure produces positive voltage at (+) pin